



Personal Protective Equipment

Basic PPE Requirements

- 1 Pair CSA Steel Toed Work Boots
(Leather / Rubber or Both)
- 2 Pairs Fire Retardant Coveralls
- 1 Bag Green King Gloves/Cloth
- 1 Hard Hat – CSA Approved
- 1 Pair of Rain Gear (Has to be Fire Retardant)
- 1 Pair of Armor Gloves

Recommended Winter PPE

- 1 Pair CSA Steel Toed Winter Boots
(With removable liners)
- 2 Pairs Fire Retardant Coveralls
- 1 Bag Green King Gloves
- 1 Pair of Armored Gloves
- 1 Hard Hat – CSA Approved
- 1 Fire Retardant Hard Hat Liner (Has to be Fire Retardant)
- 1 Pair Safety Glasses

Please note: These are recommendations only and could be subject to change at any time. Please consult your Rig Manager.

